



Vehicle History Report #: 52110382
Report Date: March 20, 2024 | 4:07 PM EDT
Report Status: Complete

2016 HYUNDAI ELANTRA SE

Sedan | 4 Cylinders | Gas
KMHDH4AE3GU494719
Country of Assembly: Korea (South)
Last Reported Odometer: 125,431 KM



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



10 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca




This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of March 20, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

KMHDH4AE3GU494719

INCIDENT DATE	DETAILS	AMOUNT
 2021 Feb 14	Etobicoke, Ontario, Canada	
	<p>Police Reported Accident: Accident reported: moderate damage Vehicle involved in a rear-end collision with another motor vehicle Damage to right rear</p> <p>Estimate: Not Available Estimate Date: 2021 Feb 19</p> <p>Claim: Collision</p>	<p>\$1,311.48</p> <p>\$1,140.00</p>



Registration

 This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2015 May 26		Streetsville Hyundai Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed Wheel locks installed Nitrogen fill tires
2015 Aug 11		Streetsville Hyundai Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Vehicle washed/detailed Nitrogen fill tires Remote start installed
2015 Dec 19	5,570 KM	Streetsville Hyundai Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> 6,000 kilometer service performed Oil and filter changed
2016 May 24	12,051 KM	Streetsville Hyundai Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Vehicle washed/detailed Oil and filter changed
2016 Oct 8	17,814 KM	Streetsville Hyundai Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed 18,000 kilometer service performed
2019 May 14	62,023 KM	Woodbine Nissan Etobicoke, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Fluids checked Oil and filter changed Tire condition and pressure checked Front brake pads replaced Air filter replaced Wiper(s) replaced Safety inspection performed Rear brake pads replaced Rear brake rotor(s) replaced Rear brakes replaced
2019 May 28		Woodbine Nissan Etobicoke, Ontario, Canada	Vehicle serviced

KMHDH4AE3GU494719

	ODOMETER	SOURCE	DETAILS
2019 Jun 25		Woodbine Nissan Etobicoke, Ontario, Canada	Vehicle serviced
2019 Nov 1	68,202 KM	Woodbine Nissan Etobicoke, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Fluids checked • Oil and filter changed • Tire condition and pressure checked
2023 Feb 21	125,431 KM	Meadowvale Honda Mississauga, Ontario, Canada	Vehicle serviced



Open Recalls

Recall #: R0254 | Trunk Latch (Interim - Recall Remedy Not Yet Available) Recall Date: 2024 Feb 23

Recall Description

Issue: On certain vehicles, a part in the trunk release latch could fail. If this happens, the emergency trunk release located inside the trunk compartment may not work properly. This could prevent a person that is trapped inside the trunk from opening it. Safety Risk: If a person is closed inside the trunk compartment, they may not be able to get out. This could create a risk of injury. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to replace the trunk latch assembly.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit [Hyundai's website](#).



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 May 26		Streetsville Hyundai Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2015 Aug 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as black
2015 Aug 11		Streetsville Hyundai Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2015 Nov 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2015 Dec 19	5,570 KM	Streetsville Hyundai Mississauga, Ontario, Canada	Service Record	Vehicle serviced

KMHDH4AE3GU494719

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 May 24	12,051 KM	Streetsville Hyundai Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2016 Oct 8	17,814 KM	Streetsville Hyundai Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2016 Nov 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Nov 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Nov 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 May 14	62,023 KM	Woodbine Nissan Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2019 May 28		Woodbine Nissan Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2019 Jun 18		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as black
2019 Jun 25		Woodbine Nissan Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2019 Sep 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Nov 1	68,202 KM	Woodbine Nissan Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2020 Sep 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black
2021 Feb 14		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> • moderate damage • Vehicle involved in a rear-end collision • with another motor vehicle • Damage to right rear
2021 Feb 14		Ontario, Canada	Collision	
2021 Feb 14	94,519 KM	Insurance Records Etobicoke, Ontario, Canada	Estimate Repair	Estimate Date: 2021-02-19 Not Available
2021 Sep 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black
2023 Feb 21	125,431 KM	Meadowvale Honda Mississauga, Ontario, Canada	Service Record	Vehicle serviced

KMHDH4AE3GU494719

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2023 Sep 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2024 Feb 23		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0254



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2024 CARFAX Canada ULC. All rights reserved.

